


No.	Function
Speed Sensor	
1	V+ (Yellow / Red)
2	Signal "B" (Blue)
3	Signal "A" (White)
4	V- / GND (Black)
Temperature Sensor	
1	Terminal "+" (Red)
2	Terminal "-" (Black)




Instruction:

- 1. Viewed from the spline end, when the alphabetical sequence of the lead terminals is the same as the power supply phase sequence, the motor rotation direction is counterclockwise.

 2. The output of speed sensor is 64 square wave pulse signals per revolution.


 3. "△" is the sign of modification.





审核REVW. BY:

日期 DATE:

4/1/15







KDS Motor